

Baru Piala bir dinding kaca borosilicate

Product Details

Item No.	SGDS16030721
Bahan	kaca borosilicate
Warna	Jelas
Kraf	Yang dihemus menggunakan mulut
Sampel masa	1. 5 hari jika pada keluar berbentuk dan saiz kaca 2. 15 hari jika perlu baru bentuk atau saiz kaca
Pembungkusan	Normal pembungkusan, 24or 36pcs ke dalam eksport kadbur, kadbur dengan kadbur pembahagi
Kapasiti produk	500, 000 ~ 1, 000, 000 unit sebulan
Masa penghantaran	Dalam tempoh 35 hari selepas sampel dan perintah yang disahkan
Terma pembayaran	deposit 30% oleh T/T lebih awal dan keseimbangan terhadap salinan B/L
Penghantaran	Tepi laut, udara, Express dan ejen penghantaran anda hanya boleh diterima

Untuk pilihan anda

1. mana-mana cetakan logo pada badan kaca
2. dicat warna apa-apa, frost, electroplate, corak carver laser bagi menyelesaikan
3. Khas pakej seperti mengecut Balut, warna kotak Hadiah, kotak hadiah putih dan lain-lain
4. terbuka baru acuan kaca, kayu, plastik atau logam seperti yang anda suka
5. berbeza saiz dan bentuk yang memenuhi keperluan anda

U"sage"

1. cemerlang semua tujuan dua dinding kaca bir
2. Jauhkan minuman sejuk minuman sejuk, panas panas
3. berkhidmat di bar atau Restoran

Peringatan

-
1. bir, wain merah, wain putih, minuman atau air panas tidak terlalu penuh dengan
 2. untuk mengelakkan untuk mencederakan tangan anak-anak anda. Sila letakkan ia di tempat di mana mereka tidak dapat mencapai
 3. Elakkan menjatuhkan, perlanggaran dan impak yang kuat
 4. tidak tersedia untuk ketuhar gelombang mikro
 5. untuk mengelakkan ia daripada keretakan, jangan letakkan ia ke atas api terbuka secara langsung

More Product Pictures





Office & Sample Room





Pensijilan



FDA

Interlock
Task Report

Date: 2023-09-15 10:00:00

Report ID: 1234567890

Subject: John Doe, Male, 30 years old, US citizen

Location: 123 Main St, Anytown, USA

Event Type: Vehicle Interlock Activation

Description: The subject was driving a vehicle with an interlock device installed. The device triggered an alarm when the subject attempted to start the vehicle without wearing a seatbelt.

Comments: The subject has been using the interlock device consistently and has no history of non-compliance.

Signature: [Redacted]

Page 1 of 3

Interlock
Task Report

Date: 2023-09-15 10:00:00

Report ID: 1234567890

Subject: John Doe, Male, 30 years old, US citizen

Location: 123 Main St, Anytown, USA

Event Type: Vehicle Interlock Activation

Description: The subject was driving a vehicle with an interlock device installed. The device triggered an alarm when the subject attempted to start the vehicle without wearing a seatbelt.

Comments: The subject has been using the interlock device consistently and has no history of non-compliance.

Signature: [Redacted]

Page 2 of 3

Interlock
Task Report

Date: 2023-09-15 10:00:00

Report ID: 1234567890

Subject: John Doe, Male, 30 years old, US citizen

Location: 123 Main St, Anytown, USA

Event Type: Vehicle Interlock Activation

Description: The subject was driving a vehicle with an interlock device installed. The device triggered an alarm when the subject attempted to start the vehicle without wearing a seatbelt.

Comments: The subject has been using the interlock device consistently and has no history of non-compliance.

Signature: [Redacted]

Page 3 of 3